



NOTES:

1. 1 1/2" - 2" TAPS SHOULD BE MADE AT THE SPRING LINE OF THE MAIN LINE.
2. SADDLE MUST BE USED IF TAP IS MADE IN PVC OR A/C PIPE.